

Berge Osnabrücker Land

Restaurierung der Rohlfing Orgel
erbaut 1907

I Manual	C - f ³
1. Bordun	8'
2. Principal	16'
3. Gamba	8'
4. Hohlflöte	4'
5. Oktave	3'
6. Rohrflöte	2'
7. Mixtur 3fach	1 3/5'
II Manual	C - f ³
10. Liebl. Gedackt	8'
11. Geigenprincipal	4'
12. Salicional	4'
13. Flauto dolce	2'
Pedal	C - d ³
17. Subbass	16'
18. Violoncello	8'

